VECTECH192 Hot gun temperature tester

Manual instruction


1.Precautions

- 1. When test temperature, test area and all around is very hot, do not touch it, avoid scald.
- 2. Do not test temperature nearby inflammable gas and inflammable object.
- 3. Keep test mouth unobstructed, strictly forbid blocking.
- 4. LCD show "1", express sensor is damage, please change new sensor.
- 5. LCD show "B", express battery is empty, please change new.

II .Describe

- 1. Testing precise, can change from °C to °F, can read test data directly.
- 2. Auto close down function, can set close down time.
- 3. Have "MAX HOLD" function.
- 4. Apply to various temperature test.

III.Picture



IV.Specification

Temperature	°C	°F
Measuring Range	(0-800) °C	(32-1500) °F
Accuracy	±5°C	±9°F
Resistance	1°C	1°F
sensor	K type sensor (NiCr-NiSi)	

LCD	Low voltage show B;		
	Sensor damage show 1		
Close down time range	0~240min		
Power life	9V battery, about 150H		
size	181 ×35× 80) mm		
wet	net: about 1KG (contain battery)		
Operation Environment	0 °C – 40 °C		

V.Operation

5.1 prepare

1. Select appropriate nozzle size, and then install temperature sensor (K type sensor in the bottom of machine), the sensor is match.

Sensor	Nozz1e	Characteristic
196-N1	850/990 series nozzle	Screw fixed
196-N2	858/997 series nozzle	Block in
196-N3-A	980 series nozzle	Small steel tube
196-NK	NK nozzle	Directly insert

2. Install battery correctly.

5.2 test nozzle temperature

- 1. Open power switch, when tester show room temperature, can start operate.
- 2. Gun hand shank insert test mouth. Set test temperature, start pre heat.
- 3. Press (°C/°F) switch, select temperature unit. F or C.
- 4. Wait moment, after numerical stability, read data.
- 5. press"MAX HOLD", LCD show "MAX HOLD". Maintain maximum temperature not change. Other function is lock until press "MAX HOLD", LCD not show "MAX HOLD".